

SAFETY RECALL

Dorel Juvenile Group Announces a Voluntary Safety Recall Of Certain Cosco[®], Safety 1st[®], Eddie Bauer[®] and Disney[®] Branded Infant Car Seat/Carriers

When used as an infant carrier, the bolts that attach the child restraint handle to the seat can loosen causing the handle to fully or partially separate from the seat creating a fall hazard.

The models affected are manufactured from January 6, 2008 through April 6, 2009. The affected models are:



The models affected are manufactured from January 6, 2008 through April 6, 2009. The affected models are: 22-057 DBY, 22-057 CLN, 22-057 HRT, 22-057 LPH, 22-085 DWA, 22-085 LYN, 22-095 RBK, 22-300 CSF, 22-300 FZN, 22-300 JJV, 22-300 OSF, 22-300 THD, 22-300 TWD, 22-305 NAB, 22-305 PPH, 22-322 HRR, 22-322 KDL, 22-322 LXI, 22-322 MAI, 22-322 OLY, 22-322 PRS, 22-322 PTK, 22-325 COB, 22-325 PAC, 22-355 LBF, 22-355 PWK, 22-380 LGA, 22-380 MSA, 22-627 AWF, 22-627 CGT, 22-627 FRK, 22-627 KGS, 22-627 SNW, 22-627 WAV, 22-627 WPR, and 22-655 BYTE.

Consumers should immediately stop using the infant seat carrying handle portion of the seat and contact Dorel Juvenile Group for a free repair kit.

For more details, visit
www.djgusa.com

and click on "Safety Notice" at the bottom of the page OR

CALL 1-866-762-3316
Monday through Friday 8:00 a.m. to 5:00 p.m. EST.