

SAFETY RECALL

ENTRAPMENT AND STRANGULATION HAZARD Simplicity Drop-side Cribs



Due to sizing problems with the crib's hardware, the drop-side can come off the tracks. When the drop-side detaches or partially detaches, it creates a hazardous gap, which can lead to infant entrapment and suffocation.

BCF.com Model Numbers

8994W
8755HT

Manufacturer's Code

This recall includes **ONLY** those units with a manufacturer's code ending with:

05DH	06GB
05GB	07DH
06DH	07GB

Model Number and Manufacturing Code can be found on headboard or footboard of the crib.

Sold from 2005 through August 2008 for around \$100 to \$300

Customers should **STOP** using this product **IMMEDIATELY** and return the product to the store where purchased for a refund or store credit.

For additional information, contact:

Recall Hotline at 800-858-8323

Between 9:30 a.m. to 5 p.m. Monday through Friday

or visit www.simplicityforchildren.com